

TYPICAL JOINERY DETAILS FOR A
MID 19TH CENTURY SASH WINDOW



